DEPARTMENT OF THE NAVY
NAVAL SUPPLY CENTER
BOX 300
PEARL HARBOR, HAWAII 96860-5300

AUG 4

IN REPLY REFER TO:

5090
Code 06
01 AUG 1988

CERTIFIED MAIL NO. P 918 275 347
RETURN RECEIPT REQUESTED

From: Commanding Officer, Naval Supply Center, Pearl Harbor
To: Hazardous Waste Program Administrator, State of Hawaii
Department of Health, Honolulu, Hawaii

Subj: INSTALLATION RESTORATION (IR) STUDY

Encl: (1) Site 6 - Naval Supply Center Pearl Harbor Red Hill Oily Waste Disposal Pit

1. Enclosure (1) is provided in accordance with Section 117 and 120 of the Superfund Amendments and Reauthorization Act of 1986. The report of the site 6 inspection concludes that the soil underlying the site is contaminated with petroleum products and it is recommended that additional samples be collected and analyzed. This will be performed in late FY88/89 timeframe.

2. The Aqua Terra Technologies under contract with the Pacific Division, Naval Facilities Engineering Command (PACNAVFACENGCOM) prepared this report and should you have any questions concerning the report's findings and recommendations, please contact Mr. Clyde Yokota of the PACNAVFACENGCOM Environmental Branch at 474-4510 or 471-3948.

E J Landerkin
E. J. LANDERKIN
By direction

carrollcox.com

carrollcox.com, Box 4202, Mililani, HI 96789 106047